

Technical Definition

Welding - Picture analysis

You shall respect the HSE policy of your laboratory for each performed test.

Instructions to participant laboratories

Please read carefully these instructions **BEFORE** starting the tests.

- 1. Three pictures are supplied to each participant The evaluations have to be performed on the files provided by e-mail.
- 2. Each participant shall list the geometric imperfections of the three pictures in accordance with **EN ISO 17639:2022**
- 3. Observations shall be performed respecting the following conditions:
 - One operator only
- 4. The following information is to be reported:

Characteristic	Unit	Significant digits	Mandatory / Not mandatory	Evaluated Yes/no
Classification of imperfection on first picture (see list below)		N/A	Mandatory	Yes

For the three pictures, please indicate the imperfections you observed among the below list:

- 1 Crack
- 2 Cavity/Porosity
- 3 Inclusions
- 4 Lack of fusion and penetration
- 5 Incomplete root penetration
- 6 Undercut
- 7 Excess weld metal
- 8 Misalignment
- 9 Spatter
- 10 Incorrect root gap for fillet welds

Imperfections will be compared to expected results.

5. Examination shall start **as soon as pictures are received**. Please contact the following e-mail address for any technical or administrative query:

Pictures available from:	February 2022	
Submission date :	June 1 st , 2022	
Technical and administrative	info@ptpscheme.com	
support :		



Technical Definition

Welding – Picture analysis

6. Instructions for submission of results are detailed on the website:

https://ptpscheme.com

7. To ensure the confidential treatment of your results in the final report, you will be allocated a unique identity number when you register for the program.

REVISION HISTORY

Iss	ue Date	Issue N°	Changes
25/	01/2022	1	Document creation
08/	04/2022	2	Modification of the test standard